


# Structurally Deficient Bridges on the National Highway System


## 16th Congressional District of Texas, 2003



Structure Number	Road	Location
240720804524005	COTTON ST	0.05 MI N SH 20

### Legend

- |  |                                |  |                     |  |                   |
|--|--------------------------------|--|---------------------|--|-------------------|
|  | Structurally Deficient Bridges |  | Interstate Highways |  | Texas District 16 |
|  | Cities                         |  | US Highways         |  | Urbanized Areas   |
|  | Airports                       |  | State Highways      |  | Park Facilities   |
|  | Amtrak Stations                |  | Amtrak Routes       |  | Military Bases    |
|  |                                |  | Other Rail Lines    |  |                   |
|  |                                |  | Navigable Waterways |  |                   |



U.S. Department of Transportation  
Bureau of Transportation Statistics  
Federal Highway Administration

The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's 2001 National Bridge Inventory. Of the 6,643 structurally deficient bridges nationwide, 416 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive safety inspections every two years. The bridges listed were categorized as structurally deficient at the time the maps were developed.